

2023 Lead in Water remediation and results

Sample Identification and location	Action Level	Initial test result	Remediation	Retest result
	5 ug/l			
Bradt				
B61 Room C5 Bubbler	5 ug/l	9.6 ug/l	Replaced bubbler	<1.0 ug/l
B71 Room D2A Sink	5 ug/l	16.0 ug/l	Replaced faucet	<1.0 ug/l
B72 Room D2A Bubbler	5 ug/l	23.3 ug/l	Replaced bubbler	<1.0 ug/l
B75 Room D3A Faucet	5 ug/l	12.2 ug/l	Replaced faucet	<1.0 ug/l
B76 Room D3A Bubbler	5 ug/l	14.3 ug/l	Replaced bubbler	<1.0 ug/l
B78 Room D4 Bubbler	5 ug/l	5.6 ug/l	Replaced bubbler	<1.0 ug/l
B79 Room D5 Sink	5 ug/l	24.9 ug/l	Replaced faucet	<1.0 ug/l
B122 PE Office Sink	5 ug/l	10.8 ug/l	Tag as hand wash only	<1.0 ug/l
B125 Room E1 Bubbler	5 ug/l	5.6 ug/l	Replaced bubbler	<1.0 ug/l
Pinewood				
P5 Kitchen Pot Filler	5 ug/l	14.9 ug/l	PERMANENTLY TAKEN OUT OF SERVICE	NA
P31 Room 8 Sink	5 ug/l	5.4 ug/l	Tagged as hand wash only/ flushed and retest	<1.0 ug/l
P34 Room 9 Bubbler	5 ug/l	9.6 ug/l	Replaced bubbler	1.8 ug/l
P17A Room 1	5 ug/l	13.1 ug/l	Tag as hand wash only, flush and retest	<1.0 ug/l
P124 Room 35	5 ug/l	7.6 ug/l	Tag as hand wash only, flush and retest	1.4 ug/l
Senior High School				
HS5 Kitchen Dishwasher Hand Sprayer	5 ug/l	11.1 ug/l	Replaced with new sprayer	<1.0 ug/l